


# Hygro-Thermometer Humidity Alert w/Dew Point

 **User Programmable Alarms**  
Warning of High or Low Humidity Conditions

## Features:


- Large, easy-to-read triple LCD displays % Relative Humidity, Temperature and Dew Point
- %RH audible and visual alarms, with adjustable set points, alert when humidity exceeds set limit
- Max/Min with Reset function
- Complete with built-in stand, wall mount bracket, and 2 AAA batteries

## Applications:

- In summertime, identifies and warns when conditions for mold growth exist
- In wintertime, identifies and warns when low humidity conditions for static electricity exist
- Air temperature and dew point temperature indicate where condensation may occur
- Monitor conditions in laboratories, storage areas and other controlled environment settings



Monitoring Dew Point levels in a Basement for potential mold growth.



Indicates Humidity and Temperature levels in Production areas.



Alerts low Humidity levels in Computer rooms to help prevent electrostatic conditions.



Checks the Humidity and Temperature levels for optimal plant growth in greenhouses.

| Specifications |                                     |
|----------------|-------------------------------------|
| Humidity       | 10 to 99%                           |
| Temperature    | 14 to 140°F (-10 to 60°C)           |
| Basic Accuracy | ±4%RH; ±1.8°F/1°C                   |
| Dimensions     | 4.3 x 3.9 x 0.78" (109 x 99 x 20mm) |
| Weight         | 6oz (169g)                          |

## Ordering Information:

445814 .....Big Digit Indoor/Outdoor Hygro-Thermometer

